Fig. 1





Fig. 2



F i g . 4 -2 RESIJLT (=Q()UT) DATAE RESET CLK DOUT

Fig. 3

| DOUT | DATAE | QOUT | DIN |
|------|-------|------|-----|
| 0 | 0 | 0 | 1 |
| 1 | 0 | 0 | 0 |
| 0 | 1 | 0 | 0 |
| 1 | 1 | 0 | 1 |
| 0 | 0 | 1 | 0 |
| 1 | 0 | 1 | 1 |
| 0 | 1 | 1 | 1 |
| 1 | 1 | 1 | 0 |

Fig. 5





Fig. 6






Fig. 8




Fig. 9

